CONTENTS

| 3. | OU I | 0-04 SITE IDENTIFICATION | 3-1 |
|------|------|--|------|
| | 3.1 | Initial Screening of WAGs 6 and 10 Sites | 3-1 |
| | 3.2 | Overview of WAG 6 Release Sites | 3-19 |
| | | 3.2.1 WAG 6 No Action Sites | 3-20 |
| | | 3.2.2 Operable Unit 6-01 | 3-21 |
| | | 3.2.3 Operable Unit 6-02 | 3-21 |
| | | 3.2.4 Operable Unit 6-03 | 3-21 |
| | | 3.2.5 Operable Unit 6-04 | 3-21 |
| | | 3.2.6 Operable Unit 6-05 | 3-22 |
| | 3.3 | Overview of WAG 10 Release Sites | 3-22 |
| | | 3.3.1 No Action Sites | 3-22 |
| | | 3.3.2 Operable Unit 10-01 | 3-23 |
| | | 3.3.3 Operable Unit 10-02 | 3-23 |
| | | 3.3.4 Operable Unit 10-03 | 3-23 |
| | | 3.3.5 Operable Unit 10-04 | 3-25 |
| | | 3.3.6 Operable Unit 10-05 | 3-25 |
| | | 3.3.7 Operable Unit 10-06 | 3-26 |
| | | 3.3.8 Operable Unit 10-07 | 3-29 |
| | 3.4 | Facility Assessment Sites | 3-29 |
| | 3.5 | CPP-66 Fly Ash Pit | 3-29 |
| | 3.6 | References | 3-30 |
| | | FIGURES | |
| | | | 2.2 |
| 3-1. | INE | EL area with WAG 10 CERCLA sites | 3-3 |
| 3-2. | EBR | EBR-I area CERCLA sites | |
| 3-3. | BOF | RAX area CERCLA sites | 3-6 |
| | | TABLES | |
| 3-1. | Alls | sites under OU 10-04, with sites assessed in the RI/FS highlighted | 3-7 |
| 3-2. | Site | descriptions and dispositions for OU 10-06. | 3-27 |

3. OU 10-04 SITE IDENTIFICATION

This section presents a general overview of the sites of concern identified in the OU 10-04 Work Plan (DOE-ID 1999a) as needing further assessment in the OU 10-04 RI/BRA. This section also includes an additional screening process in which several of these sites were eliminated from the BRA.

Sections 3.2 and 3.3 present an overview of the past activities at the WAG 6 and 10 facilities that subsequently led to releases of contamination to the environment. This is organized by OU under each WAG. Section 3.4 provides an overview of the facility assessment process included in the RI/FS. Section 3.5 discusses the CPP-66 (Fly Ash Pit) that was identified in the OU 3-13 Final ROD (DOE-ID 1999b) as an OU 10-04 site of concern for ecological receptors.

3.1 Initial Screening of WAGs 6 and 10 Sites

The initial screening of sites was performed, and the results were presented in the OU 10-04 Work Plan (DOE-ID 1999c). Sites within WAGs 6 and 10 were evaluated using the following six steps:

- 1. Information was compiled for WAG 6 and 10 sites.
- 2. New sites, unevaluated sites, and removal-action sites were identified.
- 3. No Action sites and nonsource sites were eliminated.
- 4. Sites with no detected contamination were eliminated.
- 5. Sites previously determined (through Track 1, Track 2, or other investigations) to have a risk less than 1E-07 and a hazard index (HI) less than 0.1 were eliminated.
- 6. If not eliminated by steps 3, 4, or 5, sites were retained for evaluation in the OU 10-04 RI/FS using the contaminant screening criteria.

For a detailed discussion of this process and for descriptions of the eliminated sites, see Appendices B and C of the OU 10-04 Work Plan (DOE-ID 1999c). For each site, Table 1-1 of the OU 10-04 Work Plan provided a description, described past investigations, and listed whether the site was eliminated and the reason for its elimination. In addition, Figure 3-1 shows the INEEL with the WAG 10 CERCLA sites and Figures 3-2 and 3-3 show the EBR-I and BORAX CERCLA sites, respectively. Figure 3-1 also shows all the currently identified ordnance areas including newly identified areas numbered 30 through 36. Table 3-1 of this document presents a summary of these sites. The sites of concern in this document include WAG 6 and 10 sites, facility assessment sites, and any additional sites passed forward to WAG 10 from other WAGs. During the development of this RI/FS, additional sites were eliminated. The rationale for eliminating the sites is presented in this section.




Figure 3-1. INEEL area with WAG 10 CERCLA sites.




Figure 3-2. EBR-I area CERCLA sites.




Figure 3-3. BORAX area CERCLA sites.